

General Environmental Incident Summary

Incident: 134 **Date/Time Notice:** 11/4/1991 1330 **DEM Incident No:**

Responsible Party: Cenex

Date Incident: 11/4/1991 **Time Incident:** 1300 **Duration:**

County: Pembina **Twp:** 159 **Rng:** 51 **Sec:** 23 **Qtr:** SE SW

Lat: 48.57848 **Long:** -97.17922 **Method:** Derived from TRS

Location Description: CENEX BULK PLANT

Submitted By:

Affiliation:

Address:

City:

State:

Zip:

Received By:

Contact Person: Kent Satrang

Drayton, ND 58225

Distance Nearest Occupied Building:

Type of Incident: HYDROCARBON

Description of Released Contaminant: Gasoline

Volume Spilled: 300.00 gallons

Ag Related: No

EPA Extremely Hazardous Substance:

Reported to NRC: No

Cause of Incident:

TRUCK WAS UNLOADING AT THE BULK TANK. VENT FROZE AND TANK RUPTURED. UNLOADED BULK TANK INTO TRUCKS. WILL USE ABSORBENT TO CLEAN UP. CALLED CONTRACTOR TO CLEAN SITE. RECOVERED 250 GAL OF FREE PRODUCT.

Risk Evaluation:

of Fatalities:

of Injuries:

Affected Medium:

Potential Environmental Impacts:

Action Taken or Planned:

Wastes Disposal Location:

Agencies Involved:

